

# UTILUX CUSTOM CONNECTORS

## Procedure for entering data on Forms

- Select correct form (CG, CKR, BKR, AKR, BS, CS) based on cable information from customer, ie copper, aluminium or copper to aluminium and whether a lug or a link is required.

---

### Section 1:

Tick (not X) the box to identify the standard blank which is closest to the maximum size cable.

- a. Method to select correct blank size is as follows;
  - i. Determine maximum cable size
  - ii. Select a blank that has this size in its range
  - iii. Do not worry about the smaller end size

---

### Section 2:

Fill in the conductor details, taking particular note if conductor types are outside normal metric cables.

---

### Section 3:

- a. Complete dimensions if special sizes are required
- b. Enter number of connectors required

---

### Section 4:

Complete Customer Information section in full

---

Fill in TE Internal Sale Use Only box;

- a. Part number can be taken from Cable Cross Reference
- b. Sales Order No from AMPICS
- c. Drawing number – if known
- d. Entered by – self explanatory

